
STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340

Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	General Information			
	1.	Report Time Period: From (mo./yr.) 1/95 To (mo./yr.) 1/96		
	2.	DOGM File Number (Mine No): M /003/031		
	3.	Mine Name: GROUSE CREEK MOUNTAIN		
	4.	Mineral(s) Mined (or permitted to mine): QVARTZITE TALUS		
	5.	Type of mine Surface Mine or Underground Mine		
	6.	Legal Description (Location of Lands Affected):		
	7.	Name of Operator or Company: WILLIAM L BOWN		
	8.	Permanent Street Address: 842 WEST 400 NORTH		
		City, State, Zip: <u>WEST RXXXIFUL</u> , <u>UTAH 84087</u> Phone: <u>801 - 295 - 0601</u>		
	9.	Company Representative (or designated operator):		
		Name: WILLIAM L BOWN		
		Title: OWNER		
		Business Address: 842 WEST 400 NORTH		
		City, State, Zip: WEST BOUNTIFUL, UTAH 84087		
		Phone: 801-295-0601		
		Please check if any of the above information has changed since previous year.		
II.	Minin	g and Reclamation		
	1.	Was the mine active during the past year? Yes ☑ No ☐		
	2.	If active, how much ore or mineral was mined? 100 7015		

•			
		3.	How much additional acreage was disturbed during the past year? None
		4.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
			THERE ARE NO EXCAVATIONS INCIDENT TO THIS AREA AT
			PRESENT, NO DISTURBANCES TOOK PLACE TO OUR KNOWLEDGE
			IN THE AREA. THIS IS NOT A "MINE" OR "QUARRY" LIKE
			PARK VALLEY IT, THIS AREA CONSISTS OF TALUS SLIDES, WHERE LOOS TALVS IS HAND HARVESTED.
	5.	1	TALVS IS HANO HARVESTED. How much acreage was reclaimed during the past year?
	6.		Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
	97		What is the total disturbed acreage at years end? None SEE L. KUNZLER DOG
	7.		what is the total disturbed acreage at years end: None 1500 C. None 1500
	8.		Briefly summarize any mining and/or reclamation plans for the upcoming year.
			WE HAVE PLANNED TO RECLAIM CERTAIN PORTIONS OF EX-
			ISTING ROADS, PLEASE SEE SURFACE FACILITIES MAP FURNISHED
			YOUR DIVISION INCIDENT TO PLAN OF OPERATION SUBMITTED
			12/95 TO LYMN KUNZLER.
NOTE	•		Section III., "Additional Information" applies only to large mining operations.
III. Ad	lditic	nal	Information
	1.		An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
	2.	i	Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.
IV. Sig	gnatı	ıre	Requirement
	I he	reb	by certify that the foregoing is true and correct.
			Name (Typed or Print): WILLIAM L Bown
			Title of Operator: OWNER
			Signature of Operator: William L. Bown
			1 29 - 01
īb			Date: